


EXISTING FACILITIES

FIRE STATION #2 – N MAIN St, Milan, TN

APPROACH & ENTRANCE

PARKING

There are not designated accessible parking spaces.




ENTRANCE

The side entrance into the living quarters has hardware that requires gripping or twisting. The door also closes faster than 5 seconds.



The entrance from the garage into the living area has a step.



ACCESS TO GOODS & SERVICES

INTERIOR ROUTES

While the routes are navigable they can be tight.





SIGNS

There is a lack of signage for doorways.

CONTROLS

Multiple light switches do not have a clear forward approach.



TOILET ROOM

SIGN

There is no sign at the restroom.

Also, note that there is not enough clearance on the pull side of the door.

Also, note that no grab bars are present.



LAVATORY

The mirror is higher than the minimum 40 inches.

Also, note that the paper towel dispenser is higher than 4 feet.



ADDITIONAL ACCESS

FIRE ALARM

The smoke alarm only has an audible alarm.

